

FS Fixing mounting base 30080

CE

Installation Guide:

- Drill a 6 mm Ø hole
- Wrap the DKS around the cable
- Insert DKS into FS Fixing mounting base longitudinally or in the transverse direction
- Insert the DKS with the FS into the drill hole.

Product details:

Colour:	light grey
Content pack/box	200 / 6.000



Mounting and usage instructions:

Cover the Cable(s) with DKS and insert DKS into FS Fixing mounting base. Insert DKS into a 6 mm drill hole longitudinally to the cable if fixed distance of 15 mm is requested or mount it in the transverse direction to the cable if fixed distance of 8 mm is requested. Drill. Fasten. Done!

Technical data:

Material	PP, UV stabilised Temperature range: -10 °C up to +85 °C silicon-free halogen-free
----------	---

GTIN (EAN)



With the FS Fixing mounting base in connection with the DKS Dowel clamp, the effortless mounting of thermal conduction cables with a fixed distance of 8 or 15 mm to the ceiling is possible.

Schnabl Stecktechnik GmbH
Bahnhofplatz 1, Postfach 63, 3100 St. Pölten, Austria
Telefon +43(0)2742/22167-0, Telefax +43(0)2742/22167-50
office@schnabl.works, www.schnabl.works

Stand: 2/2020

 **Schnabl**[®]
time saving products